



ಕರ್ನಾಟಕ ಸರ್ಕಾರ

ನಗರ ಪ್ರಾಥಮಿಕ ಆರೋಗ್ಯ ಕೇಂದ್ರ ಸಿಂಗಸಂದ್ರ, ಬೆಂಗಳೂರು ದ.ತಾ, ಬೆಂ. ನಗರ ಜಿಲ್ಲೆ,

E-mail-dr.singasandra@gmail.com

ಸಂಖ್ಯೆ.ಪ್ರಾ.ಆ.ಕೆ/ಸಿ/23/2025-26

ದಿನಾಂಕ:27-05-2025

Annexure C

PROFORMA FOR SAFE DRINKING WATER AND SANITARY CONDITION CERTIFICATE

It is certified that an inspection team headed by Dr.Vikas S Gowda (MEDICAL OFFICER OF UPHC SINGASANDRA AND PAPARAJU Sr.HIO) from HEALTH DEPARMENT inspected Orchids The International School,Sy no.93/2, Hommadevanahalli Village, BegurHobli, Bengaluru South Taluk, Bangalore- 560083 on 27-05-2025 (date of inspection) and on the basis of Water Test Report (Attached) bearing no-PHI/WATERBAC/149/2025-26 dated-06-05-2025 of (PHED Lab) certified that Orchids The International School,Sy no.93/2, Hommadevanahalli Village, BegurHobli, Bengaluru South Taluk, Bangalore- 560083, has safe drinking water facilities for the students and members of staff of the institution. School is also maintains the hygienic sanitation condition in the school building & the campus as per norms prescribed by the Central/ State/ U.T. Govt.

This certificate is valid till 31-03-2026

ಆಡಳಿತ ವೈದ್ಯಾಧಿಕಾರಿ  
ಪ್ರಾಥಮಿಕ ಆರೋಗ್ಯ ಕೇಂದ್ರ  
ಸಿಂಗಸಂದ್ರ, ಬೆಂಗಳೂರು-100

Signature with Seal: .....

Name : DR. VIKAS .....

Designation : .....

Name & Address of the Office / Department: UPHC Singasandra

To,

Orchids The International School,

Sy no.93/2, Hommadevanahalli Village, BegurHobli, Bengaluru South Taluk,  
Bangalore- 560083.

Note: The certificate is to be issued by authorized officer / PHED Lab / local bodies

PRINCIPAL

ORCHIDS THE INTERNATIONAL SCHOOL  
Sy. No. 93/2, Hommadevanahalli  
Village, BegurHobli, Bengaluru South, Taluk,  
Bengaluru, Karnataka 560083

For SHEKAR MEDICAL & EDUCATIONAL TRUST

Managing Trustee

**GOVERNMENT OF KARNATAKA**

**CITY PRIMARY HEALTH CENTRE, SINGASANDRA, BENGALURU SOUTH TALUK, BENGALURU DISTRICT**  
E-mail-dr.singasandra@gmail.com

No.P.H.C/C/23/2025-26

Dated: 27-05-2025

**Annexure C**

**PROFORMA FOR SAFE DRINKING WATER AND SANITARY CONDITION CERTIFICATE**

It is certified that an inspection team headed by **DR. VIKAS S GOWDA (MEDICAL OFFICER OF UPHC SINGASANDRA AND PAPARAJU Sr.HIO from HEALTH DEPARTMENT** inspected **Orchids The International School, Sy.93/2, Hommadevanahalli Village, Begur Hobli, Bengaluru South Taluk, Bengaluru – 560083** on 27-05-2025 (date of inspection) and on the basis of Water Test Report (Attached) bearing no.PHI/WATERBAC/149/2025-26 dated 06-05-2025 of (PHED Lab) certified that **Orchids The International School, Sy.93/2, Hommadevanahalli Village, Begur Hobli, Bengaluru South Taluk, Bengaluru – 560083** has safe drinking water facilities for the students and members of staff of the institution. School is also maintains the hygienic sanitation condition in the school building & the campus as per norms prescribed by the Central / State / U.T. Govt.

This certificate is valid till **31-03-2026**

**Signature with Seal**

Name : **Dr. Vikas**

Designation : **AMO**

Name & Address of the Office / Department: **UPHC SINGASANDRA**

To,

**Orchids The International School**

**Sy.93/2, Hommadevanahalli Village, Begur Hobli, Bengaluru South Taluk,  
Bengaluru – 560083.**

**PRINCIPAL**

**ORCHIDS-THE INTERNATIONAL SCHOOL  
Sy. No.93/2 situated at Hommadevanahalli  
Village, Begur Hobli, Bengaluru South, Taluk,  
Bengaluru, Karnataka 560083**

**ATTESTED TRUE COPY**

**G. DAYANANDA**

**Advocate & Notary  
Govt. of India**

**# 61, 2nd Floor, 7th Cross  
Malleshwaram  
Bangalore - 560 003**



**For SHEKAR MEDICAL & EDUCATIONAL TRUST**

**Managing Trustee**



No:PHI/Water/BAC/ 149/2025-26

GOVERNMENT OF KARNATAKA

Office of the Joint Director  
Public Health Institute  
Bengaluru - 560 001


Dated: 06/05/2025

Report of Bacteriological analysis of Water/Effluent sample

Principal orchids The inter National School sy NO 93/2, Hommadeva na Halli Village, Begur Hobli, Bangalore South Taluk, Bangalore - 83	Opinion							
	Sample No.	Source & Particulars of Water Sample	M.P.N Count	Plate Count	D.C Test	S.P.P	N.S.P.P	N.S.P.P & FC.
<b>Note:</b> <b>M.P.N Count:</b> Most probable number of Bacteria per 100ml of Water <b>D.C Test:</b> Differential Coliform test <b>Plate Count:</b> Plate Count per ml of sample <b>SPP:</b> Water is satisfactory for Potable purpose <b>NSPP:</b> Water is not satisfactory for Drinking purpose <b>NSPP &amp; FC:</b> Water is not satisfactory for Drinking purpose and E.Coli found	H64	RO Water	Nil	-	-	SPP		

  
**PRINCIPAL**  
ICHIDS-THE INTERNATIONAL SCHOOL  
No.93/2 situated at Hommadevanahalli  
ge, Begur Hobli, Bangalore South, Taluk.  
Bengaluru, Karnataka 560083

For ~~SHEKAR~~ MEDICAL & EDUCATIONAL TRUST  
  
Managing Trustee

  
For Joint Director (Labs)  
PUBLIC HEALTH INSTITUTE  
Bengaluru

(PTO)

Advice:

1. Sample.....

Need effective chlorination before use

2. Sample.....

Need to avoid possible source of faecal contamination and effective chlorination before use  
For the purpose of chlorination. Refer the Annexure enclosed.

**STANDARD FOR THE DRINKING WATER**

		Presumptive Coliform count per 100ml	E coli count per 100 ml
CLASS 1	Excellent	0	0
CLASS 2	Satisfactory	1-3	0
CLASS 3	Suspicious	4-10	0
CLASS 4	Unsatisfactory	Greater than 10	0.1 or More

PRINCIPAL  
ORCHIDS-THE INTERNATIONAL SCHOOL  
Sy. No.93/2 situated at Hommadevanahalli  
Village, Begur Hobli, Bengaluru South, Taluk.  
Bengaluru, Karnataka 560083

For SHEKAR MEDICAL & EDUCATIONAL TRUST

  
Managing Trustee